



# Operation Manual

## YarnMaster® ZENIT+ P-Matrix



---

Loepfe Brothers Ltd.  
Kastellstrasse 10  
8623 Wetzikon/Switzerland

Phone +41 43 488 11 11  
Fax +41 43 488 11 00  
E-mail [service@loepfe.com](mailto:service@loepfe.com)  
Internet [www.loepfe.com](http://www.loepfe.com)

Document title: YarnMaster ZENIT+ P-Matrix Operation Manual  
Language version: English

This Manual is protected by copyright.

Complete or partial reproduction and dissemination of this Manual to third parties – even in form of extracts – as well as the use and / or disclosure of the contents are not allowed without the written approval of Loepfe Brothers Ltd., except for internal purposes.

YarnMaster is a registered trademark of Loepfe Brothers Ltd. in Switzerland and / or in other countries.

© 2018 Loepfe Brothers Ltd., Switzerland



# Contents

<b>1</b>	<b>General Information</b>	<b>7</b>
1.1	Validity	7
1.2	Terms and abbreviations	7
1.3	Product Description	8
1.3.1	Sensing head display (7-segment display)	9
<b>2</b>	<b>Operation</b>	<b>10</b>
2.1	Finding the Optimum Setting	10
2.1.1	Selecting P default settings	10
2.1.2	Activating Test mode	11
2.1.3	Optimizing P settings	11



---

# 1 General Information

## 1.1 Validity

This document is valid for:  
YarnMaster ZENIT+ P-Matrix

## 1.2 Terms and abbreviations


The following terms and abbreviations are used in this document:

	<b>Definition</b>
P Matrix	Synthetic foreign matter matrix
P Cutting Rate	Number of P Faults per length

## 1.3 Product Description

The P matrix is used to measure the «triboelectric» yarn signal. This enables the detection of all synthetic foreign matters (on the surface), regardless of the yarn thickness:

### Graphical representation P matrix



Graphical representation P matrix

- |                                                                                                                                                                                                                      |                                                       |
|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------|
| <p>1 Vertical axis</p> <ul style="list-style-type: none"> <li>■ Intensity of charge measurement</li> </ul> <p>2 Horizontal axis</p> <ul style="list-style-type: none"> <li>■ Signal length of faults (cm)</li> </ul> | <p>3 Clearing curve</p> <p>4 Settings for P curve</p> |
|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------|



### 1.3.1 Sensing head display (7-segment display)


The sensing head display serves as setting aid for «P Cuts».

Noting the classification, when mounting the yarn faults:

- Simplifies optimizing settings.
- Prevents every single fault having to be checked at the control center.

PP			Synthetic foreign matter
P1 - P5			P classes P1 – P5
o1 - o5			P classes o1 – o5
L1 - L5			P classes L1 – L5
y1 - y5			P classes y1 – y5

Sensing head display «P Cuts»



P Matrix representation (PoLY)

i

Fine subdivision of the matrix:


- The P matrix can be divided into 4 further fields (see Y5) for an even more detailed analysis.
  - Visible in menu «Quality»: For each spindle, the last cut in the P matrix is marked in color.


## 2 Operation

### 2.1 Finding the Optimum Setting



#### 2.1.1 Selecting P default settings

✓ Menu **SETTINGS / Articles / P Settings** is displayed.

1.  Press to make changes.
2. Activate «**P Configuration**» «**Clearing**».
3. «**P Curve**» Accept proposed setting (see Fig.: Template P settings).






Template P settings

4.  Press.  
⇒ Menu **SETTINGS / Articles / Overview** is displayed.
5.  Press to save the article.  
⇒ The article is saved with the P default settings.



The intensity of the generated P Signal is not given by the thickness / magnitude of the P Faults, but is registered due to charge changes.

## 2.1.2 Activating Test mode

- ✓ Menu **SERVICE/ Diagnosis/ Test Mode** is displayed.
- 1.  Press to make changes.
- 2. Determine the timeout (Off, 30, 60, 90 or 120 min).
- 3. Select checkbox «P».
- 4.  Confirm.
- 5. Select the spindle range.
- 6.  Confirm.
  - ⇒ The selected spindles are underlined in the spindle selection list.
- ⇒ «**Test mode settings successfully transferred.**»



### Deactivating Test mode:

- Test mode is automatically deactivated after the set timeout time has elapsed.
- Test mode can be terminated prematurely by timeout «Off» as required.

## 2.1.3 Optimizing P settings

- ✓ «**Test mode**» is activated.
- 1. Wind the yarn.
  - ⇒ As soon as a P Fault is cut, the spindle is blocked.
- 2. The fault must be mounted on the yarn fault chart and analyzed (see Sensing head display (7-segment display) [▶ 9]).



### The following measures apply to all segments:

- If too many cuts are made, the clearing curve must be set higher.
- If there is no cutting at all, the clearing curve must be set lower.

- ✓ If the number of P Faults per length is not known.
- 1. Set the clearing curve lower until only the number of unauthorized cuts increases.
  - ⇒ The number of P Faults per length is known.
- 2. Set the clearing curve higher to increase clearing efficiency (fewer unauthorized cuts).
  - ⇒ The number of authorized P Cuts must remain constant.
- 3. Deactivate Test mode.
- 4. Check the cutting rate.
- 5. If necessary, make changes to the clearing curve.
  - ⇒ In practice, the number of authorized cuts should correspond to approx. 70–95 %.
- ⇒ The clearing curve is optimally defined.



Loepfe Brothers Ltd.  
8623 Wetzikon/Switzerland  
Phone +41 43 488 11 11  
Fax +41 43 488 11 00  
[service@loepfe.com](mailto:service@loepfe.com)  
[www.loepfe.com](http://www.loepfe.com)